APPENDIX B

PHOTOS



PHOTO 1 PLASTER CEILING AND RETURN AIR GRILLE LOCATED ADJACENT TO COLUMN

PHOTO 2 SPACE BETWEEN ORIGINAL PLASTER AND NEW LAY IN CEILING. NOTE SPRINKLER LATERAL LOCATION RELATIVE TO COLUMN. TYPICAL CONDITION ALONG GRIDS 2 AND 4.



PHOTO 3 TYPICAL FIRE PROTECTION AND ELECTRICAL CONDUIT IN HALLWAY. MAJORITY OF UTILITIES ARE ADJACENT TO COLUMNS.



PHOTO 4 PLASTER CEILING, FIRE PROTECTION, COMMUNICATION CABLING, AND ELECTRICAL CONDUIT. NOTE COLUMN IS PLASTERED.



PHOTO 5 RETURN AIR GRILLE LAY IN CEILING, PLASTERED CEILING COMPUTER NETWORK WIRING AND LIGHTS.



PHOTO 6 TYPICAL OFFICE ARRANGEMENT. NOTE DRAWING FLAT FILES BETWEEN COLUMN LOCATIONS.