BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 2029

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2041

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2059

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 2512A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2512B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2512C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 2512

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 900

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 2002

Homogeneous Area No. 21 Functional Space No. 17

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 3240

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area ___

Homogeneous Area No. ___ Functional Space No. ___

Category of ACM: ___ Surfacing ___ Thermal System Insulation ___ Miscellaneous

Type of Asbestos: ___ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: ___

Amount of ACM: ___

Friable: ___ Yes ___ No

Material Assessment: ___ No Damage ___ Damaged ___ Other ___

Reason for Damage: ___

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 2437

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2437A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2437C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 2421

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2405

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2405A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 135

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 2004

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2437B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 2019

Homogeneous Area No. 21 Functional Space No. 10

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3116 G

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 3415

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 3413

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3413A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3002

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 110

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3006

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 110

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3005

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 240

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301 A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 192

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 7820

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3301 N

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301 C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301 D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3301 E

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301 F

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 3114

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3301 J

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 468

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3218

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3402

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3407

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3412

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3412A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3416

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3420

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 750

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3420A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3122

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3122A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3116D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3116E

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3116F

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301G

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3301 H

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301 L

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 122

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3301 M

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 122

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3116

Homogeneous Area No. 21 Functional Space No. 5

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3116A

Homogeneous Area No. 21 Functional Space No. 10

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3116B

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3414A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3024

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 2000

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 3024A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3024B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 3024C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 3024D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3106

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4024

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 175

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4020

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4008

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4406

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4406A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4406 B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4406 C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4406 D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4016

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4419

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4413

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4413A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 30

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4413B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4413C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4413D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4015A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4019

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4023

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4039

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4027

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 85

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4027B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 60

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4435B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 85

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4435A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 60

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4105

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4114

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4110

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4414

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 60

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area ___

Homogeneous Area No. ___ Functional Space No. ___

Category of ACM: ___ Surfacing ___ Thermal System Insulation ___ Miscellaneous

Type of Asbestos: ___ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: ___

Amount of ACM: ___

Friable: ___ Yes ___ No

Material Assessment: ___ No Damage ___ Damaged ___ Other ___

Reason for Damage: ___

Area ___

Homogeneous Area No. ___ Functional Space No. ___

Category of ACM: ___ Surfacing ___ Thermal System Insulation ___ Miscellaneous

Type of Asbestos: ___ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: ___

Amount of ACM: ___

Friable: ___ Yes ___ No

Material Assessment: ___ No Damage ___ Damaged ___ Other ___

Reason for Damage: ___

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 3116C

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4447D

Homogeneous Area No. 21 Functional Space No. 7

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4045A

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 75

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4315B

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4447C

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4006

Homogeneous Area No. 21 Functional Space No. 9

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4045

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4049

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4303

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4303A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4311

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4315

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4315A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4447

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4447B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4447A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4435

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 750

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4427

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 900

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4423

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 4411

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 500

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4001

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4002

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4014

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4001A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4001 B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4009

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4013

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4017

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4021

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 4025

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 4029

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4033

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 4041

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5218

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5404

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5412

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5408

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5416

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5420

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5414A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5414B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5424

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5428

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5432

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5122

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5040

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 600

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5040 A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5040B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5110

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5022

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5020

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5020A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5020B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5020C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5020D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5020E

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5018

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5014

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5012

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5010

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5008

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5002

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5006

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5001

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5005

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5009

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5013

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5015

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5019

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5023

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5017

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5021

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5025

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5029

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5033

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5037

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5041

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 160

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5045

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5049

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 5053

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 5053A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5307

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5311

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5315

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5319

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5451

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5447

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5445

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5439

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5437

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5443

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5443A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5435

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5431

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5427

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 5425

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

F-862

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5425A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5425B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5425C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5423

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5419

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5413

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5415

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5411

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5407

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5403

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5114

Homogeneous Area No. 21 Functional Space No. 7

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5441

Homogeneous Area No. 21 Functional Space No. 7

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5218A

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5040C

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 135

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5417

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 450

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5414

Homogeneous Area No. 21 Functional Space No. 5

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5031

Homogeneous Area No. 21 Functional Space No. 9

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 750

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5449

Homogeneous Area No. 21 Functional Space No. 9

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 5039

Homogeneous Area No. 21 Functional Space No. 10

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 5445A

Homogeneous Area No. 21 Functional Space No. 18

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6425

Homogeneous Area No. 21 Functional Space No. 10

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6421

Homogeneous Area No. 21 Functional Space No. 10

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6202

Homogeneous Area No. 21 Functional Space No. 7

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1000

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6020

Homogeneous Area No. 21 Functional Space No. 9

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 450

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6024

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6027

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6025

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6029

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6031

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6033

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6039

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6037

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6041

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6045

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6053

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 600

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6307

Homogeneous Area No. 21 Functional Space No. 1

[illegible] ___ [illegible] ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6318

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6317

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 600

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6018

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6018

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6014

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6010

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6006

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6002

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6001

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6005

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 6009

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 6013

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6015

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6017

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6021

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6023

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 6424

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 6428

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6432

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6122

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6118

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6114

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6112

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6110

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6108

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6106

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6102

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6026

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6022

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6411

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6407

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6403

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6404

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6408

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6406

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6214

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6406A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6410

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 6412

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6416

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6414

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 300

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6420

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6319

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6323

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6455

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 350

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6451

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6447

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6441

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 150

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6443

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6435

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 135

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 6429

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 2400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 6427

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 650

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 6429A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 90

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 6415

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7019

Homogeneous Area No. 21 Functional Space No. 9

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 500

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7005 1/2

Homogeneous Area No. 21 Functional Space No. 10

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 65

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7403

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7027B

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 80

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7453

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7427

Homogeneous Area No. 21 Functional Space No. 2

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 180

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

F-894

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7412

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 7600

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7412A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7412B

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7412C

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 7412D

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

Area 7412E

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/A

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7412 F

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7412G

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7005

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 250

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

F-897

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7005A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7417

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1400

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7027

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 750

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

F-898

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7027A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 120

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 7017

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 1200

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

Area 7017A

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 100

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: n/a

BUILDING INSPECTION SUMMARY SHEET

Building: FEDERAL BUILDING

GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Date of Inspection: 09-13-95

Area 7037

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 650

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7039

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 800

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A

Area 7055

Homogeneous Area No. 21 Functional Space No. 1

Category of ACM: ___ Surfacing ___ Thermal System Insulation ✓ Miscellaneous

Type of Asbestos: ✓ Chrysotile ___ Amosite ___ Other ___

Percent Asbestos: 3-5%

Amount of ACM: 600

Friable: ___ Yes ✓ No

Material Assessment: ✓ No Damage ___ Damaged ___ Other ___

Reason for Damage: N/A