Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6421 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 10

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 90 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: n/a Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: CHRYSOTILE Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ___ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ✓ Other (specify) Computer / Copy

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	✓	___
Activity & Movement:	___	✓	___
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: MASTIC CONTAINS 3-5% CHRYSOTILE ASBESTOS

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6202 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 7

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 1000 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: n/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: CHRYSOTILE Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- Office
- ✓ Conference Room
- Garage
- Mechanical Area
- Hallway
- Roof
- Lobby
- Cafeteria
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:		✓	
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: MASTIC CONTAINS 3-5% CHRYSOTILE ASBESTOS

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-602

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6020 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 9

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 450 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: n/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: CHRYSOTILE Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ___ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ✓ Other (specify) Library

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	✓	___
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled	Possible	None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: MASTIC CONTAINS 3-5% CHRYSOTILE ASBESTOS

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-603

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6024 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 2

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 150 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: n/a Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: CHRYSOTILE Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ___ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ✓ Other (specify) Storage

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	___ High	___ Moderate	✓ Low
Activity & Movement:	___ High	___ Moderate	✓ Low
Change in Building Use:	___ Scheduled	___ Possible	✓ None
Vibration:	___ High	___ Moderate	✓ Low
Air Plenum:	✓ Yes	___ No	

Comments: MASTIC CONTAINS 3-5% CHRYSOTILE ASBESTOS

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-604

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6027 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 150 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-605

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6025 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other:

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-606

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6029 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	✓	___
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6031 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 150 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-608

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6033 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6039 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 400 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-610

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6037 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6041 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6045 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6053 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 600 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-614

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6307 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 350 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	None ✓
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6318 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 250 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-616

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6317 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 600 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	✓	___
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-617

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6018 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-618

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6014 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	✓	___
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6010 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-620

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6006 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-621

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6002 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-622

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6001 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6005 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-624

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6009 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6013 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-626

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6015 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 150 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-627

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6017 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-628

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6021 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High ___	Moderate ✓	Low ___
Activity & Movement:	High ___	Moderate ___	Low ✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	High ___	Moderate ___	Low ✓
Air Plenum:	Yes ✓	No ___	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6023 Date of Assessment:

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet Square Feet ✓

Area of Damaged ACM: N/A Linear Feet Square Feet

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: (Facility Asbestos Control Manager) Date:

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6424 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	None ✓
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6428 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6432 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 350 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6122 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.:
(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet Square Feet ✓

Area of Damaged ACM: N/A Linear Feet Square Feet

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: (Facility Asbestos Control Manager) Date:

F-634

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6118 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	✓	___
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6114 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 150 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-636

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6112 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 150 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-637

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6110 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6108 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 150 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-639

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6106 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	✓ Moderate	Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-640

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6102 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 400 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ____ Date: ____
(Facility Asbestos Control Manager)

F-641

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6026 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 200 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6022 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:		✓	
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6411 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-644

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6407 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-645

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6403 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6404 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6408 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-648

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6406 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 300 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled	Possible	None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6214 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 300 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6406A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 120 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-651

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6410 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 120 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-652

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6412 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6416 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	___ High	___ Moderate	✓ Low
Activity & Movement:	___ High	___ Moderate	✓ Low
Change in Building Use:	___ Scheduled	___ Possible	✓ None
Vibration:	___ High	___ Moderate	✓ Low
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-654

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6414 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 300 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-655

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6420 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-656

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6319 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-657

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6323 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	___ High	___ Moderate	✓ Low
Activity & Movement:	___ High	___ Moderate	✓ Low
Change in Building Use:	___ Scheduled	___ Possible	✓ None
Vibration:	___ High	___ Moderate	✓ Low
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6455 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 350 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-659

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6451 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-660

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6447 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6441 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 150 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	___ High	___ Moderate	✓ Low
Activity & Movement:	___ High	___ Moderate	✓ Low
Change in Building Use:	___ Scheduled	___ Possible	✓ None
Vibration:	___ High	___ Moderate	✓ Low
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-662

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6443 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 200 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6435 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 135 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6429 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 2400 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6427 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 650 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-666

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6429A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 90 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 6415 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-668

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7019 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 9

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 500 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ___ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ✓ Other (specify) LIBRARY

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7005 1/2 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 10

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 65 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ___ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ✓ Other (specify) Computer/Copy

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7403 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 2

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- ✓ Other (specify) STORAGE

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 70276 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 2

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 80 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- ✓ Other (specify) STORAGE

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-672

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD ALBUQUERQUE NEW MEXICO

Area: 2453 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 2
(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- ✓ Other (specify) STORAGE

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7427 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 2

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- ✓ Other (specify) STORAGE

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-674

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7412 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 7600 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7412A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 100 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ____ Date: ____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7412B Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 120 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-677

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7412C Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 120 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-678

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 74/21 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 120 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-679

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7412E Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 100 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 2412F Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 100 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	✓ None
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7412G Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 100 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ (None)
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-682

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7005 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 250 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-683

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7005A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 120 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-284

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 747 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 1400 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ____ Date: ____
(Facility Asbestos Control Manager)

F-685

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7027 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 750 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7027A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 120 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-687

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7017 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 1200 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7017A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 100 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-689

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7037 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 650 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7039 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 800 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ____ Date: ____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7055 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 600 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	___ High	___ Moderate	✓ Low
Activity & Movement:	___ High	___ Moderate	✓ Low
Change in Building Use:	___ Scheduled	___ Possible	✓ None
Vibration:	___ High	___ Moderate	✓ Low
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-692

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7307 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7323 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 350 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-694

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7323 A Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 200 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:	___	___	✓
Activity & Movement:	___	___	✓
Change in Building Use:	Scheduled ___	Possible ___	None ✓
Vibration:	___	___	✓
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7451 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- ___ Extension Panels
- ___ Clapboard
- ___ Asbestos/Cement Piping
- ___ Sheet Goods
- ___ Paints & Coatings
- ___ Ceiling Tile
- ___ Roofing Felt
- ___ Shingles
- ___ Millboard
- ___ Wallcovering
- ___ Other: ___

Total Amount ACM: 180 Linear Feet ___ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ___ Square Feet ___

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- ___ Mechanical Area
- ___ Lobby
- ___ Conference Room
- ___ Hallway
- ___ Cafeteria
- ___ Garage
- ___ Roof
- ___ Other (specify) ___

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:	___	___	✓
Water Damage/Deterioration:	___	___	✓
Friability of Damaged Area:	___	___	✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	___ High	___ Moderate	✓ Low
Activity & Movement:	___ High	___ Moderate	✓ Low
Change in Building Use:	___ Scheduled	___ Possible	✓ None
Vibration:	___ High	___ Moderate	✓ Low
Air Plenum:	✓ Yes	___ No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: ___ Date: ___
(Facility Asbestos Control Manager)

F-696

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7445 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-697

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7443 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: 1

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 180 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-698

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7439 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 200 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

	High	Moderate	Low
Accessibility:			✓
Activity & Movement:			✓
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:			✓
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-699

Miscellaneous Asbestos-Containing Material Assessment Form

Building: FEDERAL BUILDING GSA Bldg. No. NM0024ZZ

Address: 517 GOLD, ALBUQUERQUE, NEW MEXICO

Area: 7435 Date of Assessment: 9-13-95

Homogeneous Area No.: 21 Functional Space No.: /

(Note: A separate assessment form will be completed for each type of miscellaneous ACM)

Type of Miscellaneous ACM: (Attached separate sheets if more than one type.)

- ✓ Floor Tile
- ✓ Mastic
- Extension Panels
- Clapboard
- Asbestos/Cement Piping
- Sheet Goods
- Paints & Coatings
- Ceiling Tile
- Roofing Felt
- Shingles
- Millboard
- Wallcovering
- Other:

Total Amount ACM: 150 Linear Feet ____ Square Feet ✓

Area of Damaged ACM: N/A Linear Feet ____ Square Feet ____

Asbestos Known? ✓ Type: Chrysotile Percentage: 3-5% Asbestos Assumed? ✓

Locations:

- ✓ Office
- Mechanical Area
- Lobby
- Conference Room
- Hallway
- Cafeteria
- Garage
- Roof
- Other (specify)

Condition of ACM:

	Major	Minor	None
Physical Damage/Deterioration:			✓
Water Damage/Deterioration:			✓
Friability of Damaged Area:			✓

Potential for Future Damage, Disturbance, or Erosion:

Accessibility:	High	Moderate	✓ Low
Activity & Movement:	High	Moderate	✓ Low
Change in Building Use:	Scheduled	Possible	✓ None
Vibration:	High	Moderate	✓ Low
Air Plenum:	✓ Yes	No	

Comments: Mastic contains 3-5% Chrysotile Asbestos

Assessor: BEP/AAL Date Report Completed: 10/31/95

Signed: _____ Date: _____
(Facility Asbestos Control Manager)

F-700