1. VIEW AT HALLWAY SHOWING FLOOR SLAB DEFLECTIONS

2. MAP FILE STORAGE ROOM



3. **CRACK PATTERN IN UNDERSIDE OF FLOOR SLAB**



4. **SLOPING DESK TOP DUE TO FLOOR DEFLECTIONS**



5. **SLOPE AT FLOOR IN LENGTH OF 4 FOOT LEVEL**

6. **SLOPE AT FLOOR IN LENGTH OF 4 FOOT LEVEL**