PHOTO 1 - CRACK PATTERN AT TOP OF SLAB - LEVEL 8

PHOTO 2 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 8

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 1 & 2

PHOTO 3 - CRACK PATTERN AT TOP OF SLAB - LEVEL 8

PHOTO 4 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 8

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 3 & 4

PHOTO 5 - CRACK PATTERN AT TOP OF SLAB - LEVEL 7



PHOTO 6 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 7

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 5 & 6

PHOTO 7 - CRACK PATTERN AT TOP OF SLAB - LEVEL 7

PHOTO 8 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 7

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 7 & 8

PHOTO 9 - CRACK PATTERN AT TOP OF SLAB - LEVEL 6

PHOTO 10 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 6

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 9 & 10