

PHOTO 11 - CRACK PATTERN AT TOP OF SLAB - LEVEL 6

PHOTO 12 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 5

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 11 & 12

PHOTO 13 - CRACK PATTERN AT TOP OF SLAB - LEVEL 5



PHOTO 14 -- CRACK PATTERN AT TOP OF SLAB - LEVEL 5

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 13 & 14

PHOTO 15 - CRACK PATTERN AT TOP OF SLAB - LEVEL 5



PHOTO 16 -- CRACK PATTERN AT BOTTOM OF SLAB - LEVEL 5

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 15 & 16



PHOTO 17 - CRACK PATTERN AT BOTTOM OF SLAB - LEVEL 5



PHOTO 18 -- CRACK PATTERN AT BOTTOM OF SLAB - LEVEL 5

	ALBUQUERQUE FEDERAL BUILDING **STRUCTURAL EVALUATION** **PHOTOGRAPHS**	PHOTOS 17 & 18